

for deliveries to: Allnex Netherlands B.V. Lelyweg 21 4612 PS Bergen op Zoom Netherlands

### **General note**

Due to Allnex safety regulations and for environmental protection as well as for personal safety, please take into account the following instructions and ensure that your carrier acts accordingly.

All goods and services need to be delivered in conformity with the applicable governmental laws and regulations in particular with respect to safety, health and environment.

VIOLATION OF THESE RULES WILL CAUSE EITHER DELAYS OR REFUSAL OF THE DELIVERY!

no additional site specifics

### **Attention**

Given the high risk of contaminating resin and paint with silicones the ordered goods have to be free of aforementioned substances, in case of noncompliance we will hold you liable for all damages occurred. no additional site specifics

### Documents with goods/truck to be presented before unloading:

- Delivery note/Packing list:
- the Purchase order number of allnex
- vendor product name
- Allnex product name & code (as on allnex Purchase order)
- net weight & gross weight of delivered material
- batch number
- Packaging type & number of packages per batch (for packed goods only)
- (Multimodal) Dangerous goods transport document (if applicable)

• Bulk: In case of combined shipments in one tank truck the freight document should state the various compartments and products contained.

• Import proof in case of imported products from outside EU (all EU plants) or NO (Lillsetroem) / RU (Belgorod)

Specifics for this site are:

\* For Bergen op Zoom no combined shipments for bulk allowed

\* Silicone free statement mandatory for BoZ to be on the instruction to vendors. Attention: Given the high risk of contaminating resin and paint with silicones the ordered goods have to be free of aforementioned substances. In case of non-compliance we will hold you liable for all damages occurred.



## Documents to send beforehand (email or fax - at least 24h prior to delivery):

Certificate of Analysis (CoA)

- Required data on the COA:
- Purchase order number
- Allnex product name & code
- Vendor batch
- Expiry date
- delivered quantity
- CoA must be sent ahead of delivery to the following email address:

BOZDepBSK@allnex.com

Purchase order number in title of the mail

### Safety Data Sheet:

Please send updated SDS in local language of the Allnex destination plant for any changes: raw-material-sds@Allnex.com

no additional site specifics

## Registration at the porter / guard:

All haulers/suppliers entering Allnex Site Bergen op Zoom must register at the gatehouse.

Adhere to the safety instructions on the safety instruction folder which is given as a part of registration in the gate house as well and on-site by Allnex personnel.

### **Allnex Safety Instructions:**

**OBLIGATIONS:** 

- Follow instructions of Allnex personnel
- The general traffic regulations are applicable.
- Respect all the site procedures, instructions, sings and speed limits.
- All communication tools, except GPS must be switched off (GSM, 27MC, radio etc.) & left in the vehicle whilst on site.
- During offloading activities, the engine must be switched off, handbrake applied and chocks under wheels.
- While driving on the site, all the openings that stay in contact with the product room and also the man hole cover must remain closed

#### **PROHIBITIONS:**

- No naked flames danger of explosion!
- No smoking on site and also not allowed in drivers cabin
- Do not film and/or take pictures either whilst parked or driving on the site
- Do not enter the site under the influence of drugs, medicine or alcohol or noticeably fatigued
- Do not bring onto site any alcohol, drugs or weapons
- It is forbidden to enter plants, warehouses, laboratories and any other premises/areas not relevant for loading/unloading activities
- No passengers on site
- No pets on site
- It is forbidden to carry out activities on the truck such as cleaning, maintenance, etc.

Additonal specifics for this site are: no additional site specifics



# Communication / Language truck driver:

Communication:

Drivers must be able to understand and communicate site relevant issues in local official language of the Allnex site or English. • Driver must speak either Dutch, English or German.

### Personal Protective Equipment truck driver:

The driver must have the following Personal Protective Equipment:

- to be worn upon entering the site:

- \* Helmet
- \* Safety glasses with side protection or chemical goggles
- \* Safety shoes cat. S3
- \* Overalls or similar clothes / NO shorts and/or short sleeves
- other:
- Gloves, fit for purpose
- All PPE mentioned in the transport emergency card (Tremcard) is mandatory

• The driver must have own PPE available to access in safety conditions to the top of the truck, if needed/foreseen

Additonal specifics for this site are:

• High Visibility clothing mandatory: Vest or Jacket

## In case of emergency

The plant evacuation alarm is a loud siren. In the event of evacuation, the driver has to interrupt unloading immediately and has to go directly to the assembly area. Please check the additional specifics per site

no additional site specifics



### **Unloading packed material**

General:

\* Allnex Sites prefers deliveries of packed goods with only one batch (absolute max. accepted 2 batches). Only one batch on each pallet.

\* Allnex Sites prefers Taut-liners and Curtain-sided trailers, unloading from the side. Exemptions are temperature-controlled goods. The driver should be able to open curtains from the ground (no need for use of ladder or steps).

\* Suppler needs to ensure adequate and safe packing & marking in line with the regulation applicable in the destination country.

\*The driver must stay near the truck during unloading in presence of an ALLNEX operator

\* Drums must have cap seals.

\* Damaged goods and the thereby arising costs for the additional effort incl. cleaning in the case of a spill will be claimed at the vendor.

\* For unloading, our goods must be located in a way that we do not have to move other materials. Allnex Warehouse employees will not re-arrange products collected and shipped on the same truck for other customers as well.

### Packaging:

\* Any drum/bag etc. must be labeled with the material name, batch number, weight and relevant GHS indication for handling;

\*Big bags must be anti-static (type C) and when using an inner liner it must be well-fixed to the outer liner.

\*Big bags on pallets

\*Big bags/bags on pallets must not be stacked (exception if with an additional pallet liner in between to ensure stability)

\*Small bags must be anti-static.

Materials must be on pallets :

- Drums: CP3 pallets which must be ISPM 15 conform for shipments from outside Europe.

- Big bags/Bags: CP1 pallet whichmust be ISPM 15 conform for shipments from outside Europe.
- Only one-way-CP-pallets / no Euro pallets / no pallets with particle board blocks!

Additonal specifics for this site are:

- Boxes: CP1 or CP2 pallets

The ordered goods must be marked according to the work and transport regulations (ADR/RID/IMO/ATA) applicable in The Netherlands.

## Unloading Bulks and tank containers

\* One chamber vehicles or at least a chamber system with manifold to connect only one time the vehicle for the unloading process are required.

- \* No shared shipments with other materials on one vehicle.
- \* Required standard connections: outlet valve 3 inch Elaflex (female), gas displacement 2 inch Elaflex (male). Connections have to be mounted.
- Specific requirements for unloading of tank cars or tank container may be sent separately, as appropriate.
- \* For heated products isolated or encapsulated outlets have to be used.
- \* A handrail must be installed on tank cars and tank containers. Exceptions are ISO tank containers.
- \* The driver is not allowed to connect/disconnect any ancillary equipment to plant equipment.

\* During unloading of bulk material drivers must stay close to the outlet valve supervising the unloading process. At any point in time they have to be prepared to stop unloading in case of an emergency.

- \* Drivers are not allowed to couple/decouple the offloading connection. This must be done by an Allnex employee.
- \* Do not de-gas the tank.
- \* The driver has to wear in monitoring the discharge at least the same personal protective equipment (product covered) as Allnex staff.
- Before setting foot on a transport tank without fall protection, the driver has to be equipped with safety harness and fall stop.

• Any cleaning of trucks and tanks and any disposal of waste/ rubbish and rest product are forbidden on the site. Tank entry is forbidden on the site. After unloading all connections and man way covers need to be closed.

Additonal specifics for this site are highlighted below and/or in a spearate document.

no additional site specifics



## **Unloading hours:**

Monday to Friday, Bulk: 6.00 - 20.00, Packed: 7.30 - 17.00. Weekend only by arrangement.

### Invoice (Payer)

Allnex Netherlands B.V. Lelyweg 21 4612 PS Bergen op Zoom Netherlands

# Invoice send to:

Allnex Latvia SIA Attn: A/P Scanning Gunars Astras str.1C, 5th floor LV1084 Riga LATVIA Invoices can be sent electronically to following Email: APInvoicesEU@allnex.com

Invoices must show Purchase order number or it will be returned unpaid!

## **Delivery address**

Allnex Netherlands B.V. Lelyweg 21 4612 PS Bergen op Zoom Netherlands

# IMPORT ONLY Customs clearance agent

Depends on mode of transport and/or on individual arrangement by product. Detailed information will be provided on our Purchase Order.



# **IMPORT ONLY**

### **Customs clearance documents**

Required custom clearance documents.

- \* Invoice:
- Allnex Purchase order number
- your product name
- Allnex product name & code
- net weight & gross weight of delivered material
- batch number
- number of packages per batch (for packed goods only)
- country of origin
- customs tariff number/ HS-Code
- Incoterm & Place Incoterm
- \* Import under FTA (Free trade agreement)

- EUR1 certificate or Invoice/delivery note with preferential statement in line with the respective FTA.

\* Certificate of Origin (if requested specificly from us - see instructions on our purchase order)

- \* Import's from Oversea:
- Express Bill of Lading
- Consignee = Allnex receiving plant as on the Purchase order
- Notify Party: = Customs Clearance agent as above + Consignee + name of the Allnex contact person as on PO

Documents must be sent immediately after shipping, before arrival to the person indicated in the Purchase order. Please follow further instructions as on our Purchase order. As a consequence of absence/ incomplete custom clearance documents we will deduct the import tax from the amount invoiced.

Additonal specifics for this site are:

\* IPR requirement that all material must be customs cleared in the Netherlands

FCL: 14 day free demurrage needed

Notify II: haulier

\* Contact person as on PO should be logistics contact person